

Catch Basin Repair Pictures

Building 1 Catch Basin



This is behind building 1. The concrete portion of the basin is intact. The pavement needs to be cut back, refilled and compacted and have the supporting brick with mortar replaced , and repaved.

Another picture of Building 1 Catch Basin



Lot 5 Catch Basin



The concrete in this basin is damaged, however instead of disturbing all the banking the drainage runs through it may be best to excavate around and re-pour to make basin whole again and have added strength.